



Entrance at Kilby Street construction fence is off site, property line stakes in upper center of photo.
5-12-21



Approximate location of house pad at the time of my site visit water was visible in areas on the surface.
5-12-21



Stone channel on the site with pipe visible at the far end. Looking at Summer Street beyond construction fence.

5-12-21



Another view at the edge of Summer Street top left.

5-12-21



Location of the lower end of the infiltration basin. Note water and skunk cabbage indicating poor soils and high water table.
5-12-21



End of stone trench and 4 inch pipe past sediment barrier.
5-12-21