



Looking South at a piece of exposed ledge behind the metal plate, it is unclear where the Tree Preservation Area is relative to this ledge but it would be to the right of the ledge in the photo based on prior estimations from available fencing. The stake is not identified.

6-17-21



Looking east from the disturbed part of the lot at another piece of exposed ledge, it is unclear where the Tree Preservation Area is relative to this ledge. This is south of the prior picture and the mulch log is behind this outcrop of ledge

6-17-21



Looking North, the exposed ledge at the top of the picture is the same as in the first picture. As can be seen this is mostly fill. The ledge in the second photo taken is behind where I am standing.
6-17-21



This is a section of the older mulch log. As noted it is unclear where this is located relative to the Tree Preservation Area as it is not indicated on the plans revised 6-7-21.
6-17-21