

## Savage-Dunham, Mary

---

**From:** Dempsey, Stephen  
**Sent:** Thursday, March 7, 2019 2:58 PM  
**To:** Savage-Dunham, Mary  
**Cc:** Sarni, Susan  
**Subject:** 315 Lincoln Street

Hi Mary,

With regard to 315 Lincoln Street, As stated by Susan Sarni, an in-line external grease trap shall be installed. Additional Sewer Department requirements are as follows;

- A pre and post construction CCTV video inspection of the service connection from the building to SMH1412 must be provided to the Department. These video inspections shall be performed utilizing a robotic tilt-pan camera.
- The existing oil/water separator must be abandoned per MWRA specifications.
- The existing service connection shall be cut and capped where it meets the new PVC pipe installed by Avalon, prior to demolition.
- The existing service connection must be replaced to where it meets the new PVC pipe installed by Avalon. This replacement is required due to the age and exposure to motor oils and other industrial waste.
- A proposed sewer plan shall be submitted to the Sewer Department and Board of Health.
- All fees shall be paid in full prior to the commencement of work. The new installation shall be in compliance with all Sewer Rules and Regulations.
- All sewer work shall be performed by a drain layer licensed to work in the Town of Hingham.

Please feel free to contact me with any further questions or comments.

Thank you,



Town of Hingham Massachusetts

### Stephen Dempsey

#### Sewer Supervisor

Hingham Sewer Department  
25 Bare Cove Park Drive  
Hingham, MA 02043  
Office: (781) 741-1430  
Fax: (781) 741-1432  
[dempseys@hingham-ma.gov](mailto:dempseys@hingham-ma.gov)  
[www.hingham-ma.gov](http://www.hingham-ma.gov)